

Below are updated photos of the CSN building restoration project:

Primrose door will be painted.





Primrose prepped with 18 inch wide trench around perimeter where drain stones will be installed to eliminate pooling of rain water.



Unfortunately, 3 Red Bud trees were too close to the siding and had to be removed and stumps were ground down.



OSB installation has begun on building 1.



Vapor barrier being installed on building 1.

